
STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Gener	al Information			
	1.	Report Time Period: From (mo./yr.) Aug. 1998 To (mo./yr.) Aug. 1999			
	2.	DOGM File Number (Mine No): 510371099 UMC159118			
	3.	Mine Name: RAINBOW #1 (PICTURE ROCK QUARRY)			
	4.	Mineral(s) Mined (or permitted to mine):UNCOMMON ROCK			
	5.	Type of mine □ Surface Mine or □ Underground Mine			
	6.	Legal Description (Location of Lands Affected):			
		1/4,1/4,1/4, Section 3+4, Township 385, Range 24E			
		1/4,1/4,1/4, Section, Township, Range			
		1/4,1/4,1/4, Section, Township, Range			
7.	Name of Operator or Company: JASON B. SHUMWAY				
	8.	Permanent Street Address: 1025 S. 200 E.			
		City, State, Zip: BLANDING, UTAH 84511			
		Phone: 435-678-2909			
	9.	Company Representative (or designated operator):			
		Name: JASON B. SHUMWAY			
		Title: OWNER			
		Business Address: 1025 S. 200 E			
		City, State, Zip: BLANDING UTAH 84511			
	Phone: 435-678-2909				
		☐ Please check if any of the above information has changed since previous year.			
II.	Mining and Reclamation				
	1.	Was there any mine related activity during the past year? Yes ☑ No □			
	2.	If no - what was the last year of activity? REJECT SURFACE ROCK REMOVED AUG 1998-AUG 1999 IN PREPARATION OF RECLAIMATION WORK AND			
	3.	If yes - how much ore or mineral was mined? ASSESSMENT WORK.			

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.				
	NO ADDITIONAL DIG	• • •			
	REMOVED.	,			
5.	How much additional acreage was dis	turbed during the past year?	None		
6.	How much acreage was reclaimed duri	•			
7.	_	• • •			
	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.				
		977-1-1-1	NONE		
8.	? LESS THAN 5 ACRES				
9.	9. Briefly summarize any mining and/or reclamation plans for the upcoming year.				
DON'T KNOW					
		· · · · · · · · · · · · · · · · · · ·			
NOTE:	Section III., "Additional Information" a	pplies only to large mining	operations.		
III. Additional Information					
1.	 An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached. 				
2.					
IV. <u>Signature</u>	<u>Requirement</u>				
I hereby certify that the foregoing is true and correct.					
	Name (Typed or Print):	JASON B. SH	lumway		
	Title of Operator:	OWNER			
	Signature of Operator:	Jason B.D.	humeway		
	Date:	19-24-99			

jb a:\forms\MR-AR